

: K T - MB



K I N T E K

:

	K T - MB 2 0	K T - MB 3 0	K T - MB 3 5	K T - MB 6 0	K T - MB 6 5
RT - 1 0 0 0					
	± 1				
F E C					
	2 0 0 mm	3 0 0 mm	3 5 0 mm	6 0 0 mm	6 5 0 mm
	5 0 mm	6 0 mm	8 0 mm	8 0 mm	8 0 mm
	7	7	8	9	1 2
	7 2 0 0 mm	7 2 0 0 mm	7 2 0 0 mm	7 6 5 0 mm	1 3 3 8 0 mm