



K I N T E K F U R N A C E

R o t a r y F u r n a c e

C o n t a c t u s f o r m o r e i n f o r m a t i o n o n H i g h T e m p e r a t u r e F u r n a c e s ,

K I N T E K F U R N A C E

> > >

K i n t e k F u r n a c e

C V D / P E C V D



: K T - C R T F



1 6 0 0

	KT - CRTF12	KT - CRTF14	KT - CRTF16
	1 2 0 0	1 4 0 0	1 6 0 0
	1 1 0 0	1 3 0 0	1 5 0 0
	0 - 2 0 / min	0 1 0 /	
	/	Al2O3 / Si3N4	
	0 2 0 rpm		
	- 5 3 0		
	3 0 / 4 0 / 6 0 / 8 0 / 1 0 0 / 1 2 0 / 1 5 0 / 2 3 0 / 2 8 0 mm		
	3 0 0 / 4 5 0 / 6 0 0 / 8 0 0 mm		
	O SS 3 0 4		
	Cr2Al2Mo2	SiC	MoSi2
	K	S	B
	P I D / P I D		
	± 1		
	AC110 - 220V 50 / 60Hz		

: K T - R T F



K I N T E K :

	KT - RTF12	KT - RTF14	KT - RTF16
	1200	1400	1600
	1100	1300	1500
	0 - 20 / min	0 10 /	
	/ 310S	Al2O3 / Si3N4 / 310S	
	0 20 rpm		
	- 5 +30		
(mm)	30 / 40 / 60 / 80 / 100 / 120 / 150 / 230 / 280 (		)
mm	300 / 450 / 600 / 800		
	SS304 O		
	Cr2Al2Mo2	Mo Fe - Cr - Al	SiC MoSi2
	K	S	B
	P I D /	P I D	PLC
	±1		
	AC110 - 220V	50 / 60HZ	/

: K T - M R T F



3 6 0 °

	KT-MRTF12	KT-MRTF14	KT-MRTF16
	1200	1400	1600
	1100	1300	1500
	0-20 /min	0-10 /	
	/	Al ₂ O ₃ /Si ₃ N ₄	
	0-20 rpm		
	-5-30		
	30 / 40 / 60 / 80 / 100 / 120 / 150 / 230 / 280 mm		
	300 / 450 / 600 / 800 mm		
	2-8		
	O SS 304		
	Cr ₂ Al ₂ Mo ₂	SiC	MoSi ₂
	K	S	B
	PID / PID		
	±1		
	AC110-220V 50/60Hz		



K i n t e k F u r n a c e

8 9

W h a t s A p p
Image not found