

1 4 0 0

: K T - T F 1 4



K I N T E K

2 0 0 0

C V D

	K T - T F 1 4	K T - T F 1 4
	P I D	P I D
	1 4 0 0	
	1 3 0 0	
	A l 2 O 3	
(mm)	3 0 / 4 0 / 6 0 / 8 0 / 1 0 0 (	)
mm	3 0 0 / 4 5 0 / 6 0 0 / 8 0 0 (	)
	1 1 0	
	O S S 3 0 4	
	0 . 0 0 1 P a - 5 t o 1 0	
	0 . 0 2 M P a / 1 5 0 t o r r	
	A l 2 O 3	
	C r 2 A l 2 M o 2	S i C M o S i 2
	0 1 0 /	
	S (	)
	± 1	
	± 5	
	A C 1 1 0 - 2 4 0 V 5 0 / 6 0 H Z	

K I N T E K

2 0 0 0

No .		
------	--	--

	KT - TF14	KT - TF14
1		1
2		1
3		2
4	/	2
5	/	1
6		1
7		1